




AC Power Connection

The AC power adapter plugs into a hole on the front of the fly wheel. The hole looks similar to a hole meant for a screw.



For more information please contact our SOLE Service Department.

www.soletreadmills.com

service@soletreadmills.com

866-MYSOLE1 (866-697-6531)